

# General Environmental Incident Summary

**Incident:** 3478      **Date/Time Notice:** 9/27/2014      1733      **DEM Incident No:**

**Responsible Party:** Ramesh Majhi

**Date Incident:** 9/27/2014      **Time Incident:** 1454      **Duration:**

**County:** Cass      **Twp:** 139      **Rng:** 49      **Sec:** 16      **Qtr:**

**Lat:** 46.85571      **Long:** -96.86834      **Method:** Interpolation from map

**Location Description:** 4830 16 Ave SW Fargo ND 58103

**Submitted By:** Daren Wawrzyniak

**Affiliation:**

**Address:** 4100 32nd Ave S

**City:** Fargo

**State:** ND

**Zip:**

**Received By:**

**Contact Person:**

1537 48th St S #103

Fargo , ND 58103

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** Non PCB - mineral oil

**Volume Spilled:** 5.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

Car pushed transformer off of pad in front yard of apartment building. This caused the top bushing to break resulting in oil leak.

**Risk Evaluation:**

None

**# of Fatalities:**

**# of Injuries:**

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

None, oil spill was cleaned up to the best of our ability.

**Action Taken or Planned:**

Removed saturated soil and soaked up oil on concrete with spill pads. An oil sample will be pulled and sent in for testing per our procedure.

**Wastes Disposal Location:** Land fill once oil sample results are received.

**Agencies Involved:**

## **Updates**

---

**Date:** 9/27/2014    **Status:** Reviewed - Assigned to NDDoH Division

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Transformer damaged and leaking, due to car accident. According to the report, the leaked dielectric oil has been cleaned up, and a sample was taken. Forwarded to Division of Waste Management.

---

**Date:** 10/2/2014    **Status:** Inspection

**Author:** Tintes Schiwal, Emily

**Updated Volume:**

**Notes:**

Hunter Hubrig from the City of Fargo inspected the incident location and did not find any trace of the oil left around the transformer. CCEC removed all stained soils and rocks and replaced with clean material.